100

finish portion 100C

end-of-line portion 100B

front-of-line portion 100A

FIGURE 1



. -




FIGURE 2

٤.

in-line front-of-line portion 300A

V/C 302 V/C 302

1	D/A	cure	plasma	W/B	plasma
			308	310	312
	304	306	300		L

in-line end-of-line portion 300B

V/C	V/C
302	302

mold	PMC	SBA	saw	sort
314	316	318	320	322

V/C 302

in-line finish portion 300C

V/C	V/C	V/C
302	302	302
mark	FVI	T/R
324	326	328






Figure 4



Flgure 5

FIGURE 6







FIGURE 8






FIGURE 10





FIGURE 12



7-16 13